



STAPLES AND WIRE ATTACHMENT




(WIRE PULL IS DOWN)


DRIVE  
STAPLES  
AT ANGLE




DO NOT DRIVE  
STAPLES PARALLEL  
TO SIDE OF POST



LEAVE  
WIRE LOOSE  
IN STAPLE






a) No. 9 gauge bright  
U-shaped staple,  
1-3/4"




b) No. 9 gauge bright  
L-shaped deformed  
shank staple, 1-1/2"

ATTACHMENT

STAPLES



STEP 1



splice may be  
made with  
pliers

STEP 2



completed splice

STEP 3

"WESTERN UNION" SPLICE

JOB CLASS

Date

CAD FILE NO.  
LSK-0001.DWG

Designed \_\_\_\_\_

Drawn \_\_\_\_\_

SHEET OF

Checked \_\_\_\_\_

Approved \_\_\_\_\_